

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

Applicant: YU et al.  
Title: METHOD OF SIGNAL SUBSTITUTION FOR  
MAINTENANCE OF AMPLIFIER SATURATION  
Appl. No.: Unassigned  
Filing Date: August 28, 2001  
Examiner: Unassigned  
Art Unit: Unassigned

**TRANSMITTAL OF FORMAL DRAWINGS**

Commissioner for Patents  
Washington, D.C. 20231

ATTENTION: DRAWING REVIEW BRANCH

Sir:

Transmitted herewith are the formal drawings (11 sheets, Figures 1-10(b)) for the above-identified application. The Official Draftsperson is respectfully requested to approve these drawings for entry into the application.

Respectfully submitted,

Date

8/28/01

By

Johnny A. Kumar

FOLEY & LARDNER  
Washington Harbour  
3000 K Street, N.W., Suite 500  
Washington, D.C. 20007-5109  
Telephone: (202) 672-5489  
Facsimile: (202) 672-5399

Johnny A. Kumar  
Attorney for Applicant  
Registration No. 34,649

Title: METHOD OF SIGNAL  
SUBSTITUTION FOR MAINTENANCE  
OF AMPLIFIER SATURATION

Inventor(s): YU et al.  
DOCKET NO.: 033337-0117




FIG. 1(a)

Title: METHOD OF SIGNAL  
SUBSTITUTION FOR MAINTENANCE  
OF AMPLIFIER SATURATION

Inventor(s): YU et al.  
DOCKET NO.: 033337-0117




FIG. 1(b)

Title: METHOD OF SIGNAL  
SUBSTITUTION FOR MAINTENANCE  
OF AMPLIFIER SATURATION

Inventor(s): YU et al.

DOCKET NO.: 033337-0117




FIG. 2

Title: METHOD OF SIGNAL  
SUBSTITUTION FOR MAINTENANCE  
OF AMPLIFIER SATURATION

Inventor(s): YU et al.  
DOCKET NO.: 033337-0117




FIG. 3

Title: METHOD OF SIGNAL  
SUBSTITUTION FOR MAINTENANCE  
OF AMPLIFIER SATURATION

Inventor(s): YU et al.  
DOCKET NO.: 033337-0117




FIG. 4

Title: METHOD OF SIGNAL  
SUBSTITUTION FOR MAINTENANCE  
OF AMPLIFIER SATURATION

Inventor(s): YU et al.  
DOCKET NO.: 033337-0117





FIG. 5

Title: METHOD OF SIGNAL  
SUBSTITUTION FOR MAINTENANCE  
OF AMPLIFIER SATURATION

Inventor(s): YU et al.  
DOCKET NO.: 033337-0117








FIG. 7 (a)




FIG. 7 (b)

Title: METHOD OF SIGNAL  
SUBSTITUTION FOR MAINTENANCE  
OF AMPLIFIER SATURATION

Inventor(s): YU et al.  
DOCKET NO.: 033337-0117




FIG. 8 (a)




FIG. 8 (b)

Title: METHOD OF SIGNAL  
SUBSTITUTION FOR MAINTENANCE  
OF AMPLIFIER SATURATION

Inventor(s): YU et al.  
DOCKET NO.: 033337-0117




FIG. 9 (a)




FIG. 9 (b)

Title: METHOD OF SIGNAL  
SUBSTITUTION FOR MAINTENANCE  
OF AMPLIFIER SATURATION

Inventor(s): YU et al.  
DOCKET NO.: 033337-0117




FIG. 10 (a)




FIG. 10 (b)